

# **IMPULSE®Link™ 4.0**

## Release Notes

Current Version : 4.0.18

|  |   |
|--|---|
| CHANGES BETWEEN 4.0.17 AND 4.0.18 INCLUDE: .....               | 2 |
| Maintenance Update (Dell Computers, Communication Issues)..... | 2 |

|  |   |
|--|---|
| CHANGES BETWEEN 4.0.16 AND 4.0.17 INCLUDE: .....               | 2 |
| Software Support Update (8001.4, 8120.2, 8140.2, 8180.2) ..... | 2 |

## Changes between 4.0.17 and 4.0.18 include:

### 4.0.18 [4/04/2007]

Maintenance Update (Dell Computers, Communication Issues)

- This Update provides the following:
  - Fix: Communication problems had been occurring on a number of newer Dell PCs and laptops with Windows XP or Windows 2000 installed. Impulse Link received notification that the COM port has opened before it actually does.. reads and writes via the MSCOMM Control produce unpredictable behaviour. A default delay of 250 ms has been added between opening the COM port and beginning the upload or download. If the problem persists, this value can be adjusted through the INI file ( i.e. ESUARTDELAY=500 would set the delay for 500 ms)

## Changes between 4.0.16 and 4.0.17 include:

### Version 4.0.17 [11/03/2006]

Software Support Update (8001.4, 8120.2, 8140.2, 8180.2)

- This Update provides support for:
  - G+/VG+ Series 3 Software 8001.4
  - G+/VG+ Series 3 Software 8120.2
  - G+/VG+ Series 3 Software 8140.2
  - G+/VG+ Series 3 Software 8180.2